

Certification date: Expiry date: Certificate number: IATF Certificate number: 15 September 2021 14 September 2024 10391940 0424974

# **Certificate of Approval**

This is to certify that the Management System of:

### **PTI DOS Diversified Outsourcing Solutions, S. de R.L. de C.V.**

Av. Comerciantes Nº 1300, Parque Industrial FIPASI, 36270 Silao, Guanajuato, Mexico

has been approved by Lloyd's Register to the following standards:

### IATF 16949:2016 (excluding product design)

Approval number(s): IATF 16949 - 00016407-001

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

**The scope of this approval is applicable to:** Service of Underbody Chassis Coatings.

Ciffs A Muckeling

Cliff Muckleroy Area Operations Manager Americas Issued by: Lloyd's Register Quality Assurance Limited



Lloyd's Register Group Limited, its affiliates and subsidiaries, including Lloyd's Register Quality Assurance Limited (LRQA), and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: Lloyd's Register Quality Assurance Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



00016407-001 0424974

## **Certificate Schedule**

Location

Activities

Extended Manufacturing Site Acceso III #3, Parque Industrial Benito Juarez, 76089 Santiago de Queretaro, Mexico IATF 16949:2016

Service of Underbody Chassis Coatings.

#### PTI DOS Diversified Outsourcing Solutions S. de R.L.

Av. Fresno N° 233, Parque Industrial y de Negocios Las Colinas, 36270 Silao, Guanajuato, Mexico

#### IATF 16949:2016

Management Review, Internal Audit Management, Continuous Improvement, Quality System Management, Sales, Process Design, Supplier Management, Human Resources, Maintenance, Contract Review, Customer Service, Engineering, Finance, Information Technologies, Policy Making, Purchasing, Strategic Planning, Training.



Lloyd's Register Group Limited, its affiliates and subsidiaries, including Lloyd's Register Quality Assurance Limited (LRQA), and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: Lloyd's Register Quality Assurance Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom